

VALUE AND RELIABILITY

MERITOR® RED MANUAL SLACK ADJUSTERS



MERITOR®







VALUE AND RELIABILITY

For over 100 years we have been a leader in axle and braking systems for heavy vehicles. Meritor Red is an extended range of aftermarket braking components brought to you by one of the industry's most trusted names. Our Meritor Red Manual Slack Adjusters are the latest addition to the line-up that delivers confidence and reliability you can count on.

FEATURES AND BENEFITS

FEATURES	BENEFITS
<ul style="list-style-type: none"> Large 19mm adjusting nut is standard across the range 	<ul style="list-style-type: none"> Easier adjustment in adverse and dusty environments and where material build up on the adjuster mechanism is a problem. Only one spanner required to adjust in mixed fleet applications.
<ul style="list-style-type: none"> Heavy duty worm gear material 	<ul style="list-style-type: none"> Durability and longevity of the adjusting mechanism in real world applications.
<ul style="list-style-type: none"> Maximum torque rating 22,000 inch-pounds Approved to Meritor Standards 	<ul style="list-style-type: none"> Proven performance and long life.
<ul style="list-style-type: none"> Large 1/8" bsp lube fitting 	<ul style="list-style-type: none"> Suit auto grease system tubes

SPECIFICATIONS

PART NO.		ARM LENGTH	STRAIGHT /OFFSET	SPLINE DIA. & NO. OF TEETH	CLEVIS PIN DIA.	APPLICATION	CROSS REFERENCE	
		CAM CENTRE TO CLEVIS PIN HOLE(S)					ATAP	WATTS
MMSA5020		HOLE 1 (5") HOLE 2 (6") HOLE 3 (7")	STRAIGHT	1-1/2"-10	1/2"	GENERAL PURPOSE TRUCK & TRAILER	BP5020-1	WT5020HD
MMSA5021		HOLE 1 (5") HOLE 2 (6") HOLE 3 (7")	STRAIGHT	1-5/8" - 37	1/2"	FRUEHAUF PRO-PAR	BP5021	WT5021-3HD
MMSA5022		HOLE 1 (120 MM) HOLE 2 (150 MM) HOLE 3 (180 MM) HOLE 4 (220 MM) HOLE 5 (250 MM)	STRAIGHT	1-1/2" - 10	1/2"	BPW AXLES	BP5022	WT5022
MMSA5023		HOLE 1 (5-1/2") HOLE 2 (6-1/2")	STRAIGHT	1-1/2"-10	1/2"	DRIVE AXLES	BP5023-1	WT5023HD
MMSA5024		HOLE 1 (5-1/2") HOLE 2 (6-1/2")	STRAIGHT	1-1/2"-28	1/2"	DRIVE AXLES	N/A	WT5024HD
MMSA5025		HOLE 1 (5") HOLE 2 (6") HOLE 3 (7")	STRAIGHT	1-1/2"-28	1/2"	DRIVE AXLES	BP5025-1	WT5025HD

MMSA = Meritor Manual Slack Adjuster



Meritor Heavy Vehicle Systems Australia
 50 Calarco Drive
 Derrimut, VIC 3026
 AUSTRALIA

 (03) 8353 6050

 cummins.com | meritorpartsxpress.com

 CFL083- RED SLACK ADJUSTERS 01/25
 Produced in AUS 01/25
 ©2025 Cummins Inc.