


# MERITOR® CALIPER SERVICE KIT UPDATE

## Service Kits for ELSA225 Calipers on Scania Applications

Cummins focuses to serve its customers with the right product, at the right time ensuring the appropriate service solutions are available when you need them most, at the price you need, ensuring the service of your vehicle throughout its lifecycle.

We are pleased to announce the introduction of our ELSA225 reman caliper range & genuine Original Equipment service kits for SCANIA applications 2016 onwards.

### Meritor Remanufactured Calipers




### Meritor Genuine OE Service Kits



Sales Reference		MXC9309066	MXC9309067	MXC9309068	MXC9309069
Pad Carrier Mounting		Axial – RH	Axial – LH	Tangential – RH	Tangential – LH
OE Caliper Ref		2272727, 2499324, 2493085, 2564031, 573087	2272728, 2499325, 2493084, 2564032, 573088	2564041, 2471416, 573045	2564042, 2471417, 573073
Meritor OE Caliper Ref		68034856, 68035141, 68035125	68034857, 68035142, 68035126	68035149	68035150
Fitment Dates		2014 - 03/2016, 02/2016 >>		09/2016 >>	
Kit	Kit Position	Kit Ref			
Pad Retainer Kit	6, 7	MCK1519			
Housing Kit	7, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21	MCK1565	MCK1566	MCK1575	MCK1576
Bridge Kit	1, 14, 7	MCK1552		MCK1540	
Carrier Kit	2	MCK1513		MCK1635	MCK1636
Guide Pin Kit	14, 15, 16, 17, 18, 21, 22, 23, 24, 25	MCK1323			
Guide Pin Seal Kit	14, 18, 21, 22, 24	MCK1310			
Piston Head Kit	19, 20	MCK1309			
Piston Seal Kit	19	MCK1139			
Actuator Seal	10	68323746PK10			
Adjuster Stem Excluder	11	68322655PK10			
Visual Wear Indicator	8	MCK1311		Not fitted	

# SERVICE KITS FOR ELSA225 CALIPERS ON SCANIA APPLICATIONS



# SERVICE KITS FOR ELSA225 CALIPERS ON SCANIA APPLICATIONS

**MCK1519 - Pad Retainer Kit**



Pos	Kit Contents
6	Pad retaining plate
7	Retaining plate screw

**MCK1565, MCK1566 - Housing Kit**



Pos	Kit Contents
7	Retaining plate screw
9	Housing – includes: 10, 11, 12, 13, 15, 16, 17, 19, 20
14	Bridge screw
18	Guide sleeve excluder
21	Guide pin end cap

**MCK1323 - Guide Pin Kit**



Pos	Kit Contents
14	Bridge screw
15	Oval bush
16	Plain bush
17	Excluder retainer
18	Guide sleeve excluder
21	Guide pin end cap
22	Short guide sleeve screw
23	Short guide sleeve
24	Long guide sleeve screw
25	Long guide sleeve

**MCK1310 - Guide Pin Seal Kit**




Pos	Kit Contents
14	Bridge screw
18	Guide sleeve excluder
21	Guide pin end cap
22	Short guide sleeve screw
24	Long guide sleeve screw

**MCK1575, MCK1576 - Housing Kit**



Pos	Kit Contents
7	Retaining plate screw
9	Housing – includes: 10, 11, 12, 13, 15, 16, 17, 19, 20
14	Bridge screw
18	Guide sleeve excluder
21	Guide pin end cap

**MCK1552 - Bridge Kit**



Pos	Kit Contents
1	Bridge
7	Retaining plate screw
14	Bridge screw

**MCK1309 - Tappet/PistonHead Kit**




Pos	Kit Contents
19	Tappet/Piston excluder
20	Tappet/Piston head

**MCK1139 - Tappet/Piston Seal Kit**




Pos	Kit Contents
19	Tappet/Piston excluder

**MCK1540 - Bridge Kit**




Pos	Kit Contents
1	Bridge

**MCK1513 - Carrier Kit**



Pos	Kit Contents
2	Carrier

**68323746PK10 - Actuator Seal Ring Kit**




Pos	Kit Contents
10	Actuator seal

**68322655PK10 - Adjuster Stem Excluder Kit**




Pos	Kit Contents
11	Adjuster Cap

**MCK1635 - Carrier Kit**




Pos	Kit Contents
2	Carrier

**MCK1636 - Carrier Kit**




Pos	Kit Contents
2	Carrier

**MCK1311 - Visual Pad Wear Indicator**



Pos	Kit Contents
8	Visual wear indicator

# SERVICE KITS FOR ELSA225 CALIPERS ON SCANIA APPLICATIONS

		
<b>Scania</b>		
	2272727	<b>MXC9309066</b>
	2272728	<b>MXC9309067</b>
	2499324	<b>MXC9309066</b>
	2493085	<b>MXC9309066</b>
	2564031	<b>MXC9309066</b>
	573087	<b>MXC9309066</b>
	2499325	<b>MXC9309067</b>
	2493084	<b>MXC9309067</b>
	2564032	<b>MXC9309067</b>
	573088	<b>MXC9309067</b>
	2564041	<b>MXC9309068</b>
	2471416	<b>MXC9309068</b>
	573045	<b>MXC9309068</b>
	2564042	<b>MXC9309069</b>
	2471417	<b>MXC9309069</b>
	573073	<b>MXC9309069</b>
<b>Meritor</b>		
	68034856	<b>MXC9309066</b>
	68034857	<b>MXC9309067</b>
	68035141	<b>MXC9309066</b>
	68035125	<b>MXC9309066</b>
	68035142	<b>MXC9309067</b>
	68035126	<b>MXC9309067</b>
	68035149	<b>MXC9309068</b>
	68035150	<b>MXC9309069</b>

Vehicle models, trademarks, brands and names depicted herein are the property of their respective owners, and may not be associated with Cummins Inc. and Meritor, Inc. or its affiliates.



Cummins Inc.  
Box 3005  
Columbus, IN 47202-3005  
U.S.A.

[cummins.com](http://cummins.com) | [MeritorPartsXpress.com](http://MeritorPartsXpress.com)

Bulletin SP-2418 Produced in U.K. 8/24  
©2024 Meritor, Inc.