

## SOP #22-002

# **CORE MANAGEMENT PROCESS**

OEM selling dealers are required to follow the core management process outlined below:

### 1. Core charge upfront fee

Core Charge of AUD 1,500 /USD 1,000 per core will be collected upfront from OEM upon sale of every new carrier. A single invoice, combining new carrier and core will be supplied for each carrier transaction.

#### 2. Evidence of Core Destruction

OEM Dealers must submit proof of core destruction to CDBS Australia within 15 months from the invoice date. Failure to provide acceptable evidence or submitting inadequate documentation may result in liability for the core charge.

#### 3. Core Charge Credit

Upon successful review of the submitted evidence, the core charges AUD 1,500 /USD 1,000 will be credited to the OEM's account in full, with no interest accrual.

#### **DESTRUCTION PROCESS**

- Ensure core housing and crown wheel are damaged by appropriate means eg. oxy torch or angle grinder as shown in Fig 1. Please ensure special PPE is worn at all times during the time of core destruction.
- Take photo of destructed unit along with serial number demonstrating damage as shown in Fig 2.
- Email the Core destruction form FM-0021 and photos to <a href="mailto:coresaus@cummins.com">coresaus@cummins.com</a> with clearly visible serial number.
- You will then receive an email from Cummins confirming authorisation has been completed.
- · You can now proceed to scrap the core.



#### **BEFORE DESTRUCTION**



Housing

Crown Wheel

Serial Number

#### **AFTER DESTRUCTION**



Fig 1. Destruction of Housing/Crown Wheel

Fig 2. Visible serial number




Fig 3. Core Destruction Authorisation Form